Hendrik

**Hendrik Meijer Library Information Technology Center** 

8/11/2010

## **Building Rating System**

		Possible	Earned	Percent					
Site	Site:								
1.0	Total Points	200	172	86%					
Buil	Building:								
2.1	Building Exterior Elements	100	80	80%					
2.2	Accessibility	100	98	98%					
2.3	Structural	100	96	96%					
2.4	Building Envelope	100	99	99%					
2.5	Interior / Finishes	135	134	99%					
2.6	Life Safety	100	80	80%					
2.7	Food Service	0	0	#DIV/0!					
2.8	Mechanical	190	190	100%					
2.9	Electrical	130	111	85%					
Totals:		1155	1060	92%					

Building conditions are generally gauged on a standard model called a Facility Condition Index or FCI. An FCI is a condition indicator that calculates the cost of repair/renovation vs. the cost of replacement of a like facility. A general planning assumption is that if the cost of repairing/renovating a facility exceeds two-thirds (2/3 or 66%) the costs of replacing the facility, the facility should be considered for replacement

ASSUMED BUILDING REPLACEMENT COSTS (BASED ON \$170 / SF FOR CONSTRUCTION)
CALCULATED COSTS OF RECOMMENDED RENOVATIONS

FCI INDEX (COST OF REPAIR/RENOVATION vs. COST OF REPLACEMENT)

\$	7,140,000
\$	-
0%	




He	endrik Meijer Library I	nformation Techn	ology C	enter	8/11/2010
Building Data Building Name: Street Address:	Record  Hendrik Meijer Library I				
Building Data:	Original Construction: Additions/Renovations: Number of Floors: Building Area:	s: N/A		_ Building C	apacity:te Area:
Types of Construction	on:	Bearing Masonry Wood		Steel Frame Other	Concrete Frame
Exterior Surfacing:		Brick Wood		Metal Other	Stucco
Floor Construction:		Structural Slab Wood Joists		Steel Joists  Other	Slab on Grade
Air Conditioning:		Roof Top Room Units		Window Units	Central
Heating:		Roof Top Room Units		Forced Air	Central Hot Water
Electrical Service:	480/277V	Aerial Secondary Voltage:	3	Underground Phase:	Primary 7200/12470V  4 Wire:
Generator:		Exists None		Natural Gas	Diesel



Meijer LIT Center 8/11/2010

# Aerial Photography

0



	Hendrik Meijer Library Information Technology Center	8/11/2010
1.0	Building Site	200 Points
		Possible Earned
1.1	Site is large enough to meet present needs and future needs.	25 20
1.2	Separation of bus, car and pedestrian traffic is adequate for the safety of occupants.	25 22
1.3	Site has stable, well drained soil with no signs of erosion. Storm water management is effective.	25 20
1.4	Pedestrian services include adequate sidewalks with crosswalks, curb cuts, etc.	20 16
1.5	Condition of Pedestrian services include sidewalks, curb cuts, etc.	15 15
1.6	Sufficient on-site parking is provided for all occupants	20 17
1.7	Condition of on-site parking	15 12
1.8	Vehicular entrances and exits permit safe traffic flow.	20 15
1.9	Outdoor facilities are adequate and accessible	15 15
1.10	Condition of Outdoor facilities	20 20
TOT	AL - Building Site	200 172

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Hendrik Meijer Library Information Technology Center	8/11/2010
2.1 Building Exterior Elements	100 Points
	Possible Earned
2.1.1 Exterior building / site signage is adequate.	15 12
0.4.0 Landacaning is adaptists and appropriate	20 40
2.1.2 Landscaping is adequate and appropriate.	20 12
2.1.3 Site and entry are well defined.	20 16
2.1.4 Entrances are sheltered from inclement weather.	20 20
2.4.5. Overall code annual /Dividing and Cital	25 20
2.1.5 Overall curb appeal (Building and Site)	25 20
TOTAL Building Exterior Flaments	100 80
TOTAL - Building Exterior Elements	100 00

**Notes:** Brick and stone exterior

Some green roof areas

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Hendrik Meijer Library Information Technology Center	8/11/2010
2.2 Accessibility	100 Points
2.2.1 Exterior Walks and drives contain barrier-free curb cuts for building accessibility.	Possible Earned 10 10
2.2.2 Barrier-Free parking is provided.	10 8
2.2.3 Outdoor areas and structures are on accessible routes.	20 20
2.2.4 Building entrances and exits are barrier-free.	20 20
2.2.5 Toilet rooms are on accessible routes and designed to meet barrier-free codes.	20 20
2.2.6 Occupied spaces are accessible and are on accessible routes.	20 20
TOTAL - Accessibility	100 98

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Meijer LIT Center	8/11/2010
2.3 Structural	100 Points
2.3.1 Condition of the roof.	Possible Earned  25  22
2.3.2 Condition of the (visible) foundations.	25 25
2.3.3 Condition of exterior and interior walls.	25 24
2.3.4 Structure is non-combustible.	25 25
TOTAL - Structural	100 96

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Hendrik Meijer Library Information Technology Center	8/11/2010
2.4 Building Envelope	100 Points
	Possible Earned
2.4.1 Wall insulation is adequate.	15 15
2.4.2 Roof insulation is adequate.	15 15
2.4.3 Condition of exterior wall finishes, masonry, siding, etc.	15 14
2.4.4 Condition of exterior windows.	15 15
2.4.5 Condition of exterior doors and frames.	10 10
2.4.6 Exterior glass is insulated.	15 15
2.4.7 Openings / penetrations are sealed.	5 5
2.4.8 Building has proper amounts of daylighting.	10 10
TOTAL - Building Envelope	100 99

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Meijer LIT Center	8/11/2010
2.5 Interior / Finishes	150 Points
	Possible Earned
2.5.1 Condition of toilet rooms.	20 20
2.5.2 Condition of flooring.	20 20
2.5.3 Condition of ceilings.	20 20
2.5.4 Condition of walls.	15 15
2.5.5 Condition of equipment.	15 14
2.5.6 Condition of doors and hardware.	15 15
2.5.7 Condition of casework.	15 15
2.5.8 Condition of visual display boards.	15 15
2.5.9 Condition of lockers.	0 0
TOTAL - Interior / Finishes	135 134

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Hendrik Meijer Library Information Technology Center	8/11/2010
2.6 Life Safety and Security	100 Points
	Possible Earned
2.6.1 Fire alarm system is up-to-date and adequate for building served.	15 14
2.6.2 Fire sprinkler system installed throughout building.	15 15
2.6.3 Security system is installed throughout building.	10 5
2.6.4 Card access control system is installed.	10 4
2.6.5 Security camera system is installed.	15 7
2.6.6 There are at least two independent exits from any point in the building.	10 10
2.6.7 Egress stairways are adequate.	10 10
2.6.8 Exterior doors open outward and are equipped with panic hardware.	5 5
2.6.9 Classroom doors are adequate for egress requirements.	5 5
2.6.10 Corridors lead to an exit or exit stair.	5 5
TOTAL - Life Safety and Security	100 80

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Hendrik Meijer Library Information Technology Center	8/11/2010
2.7 Food Service	0 Points
	Possible Earned
2.7.1 Condition of flooring.	0 0
2.7.2 Condition of ceilings.	0 0
2.7.3 Condition of walls.	0 0
2.7.4 Condition of lighting.	0 0
2.7.5 Condition of kitchen equipment.	0 0
2.7.6 Dry storage requirements vs. code	0 0
2.7.7 Refrigerated storage requirements vs. code	0 0
2.7.8 Condition of serving equipement.	0 0
2.7.9 Overall flow of food service.	0 0
TOTAL - Food Service	0 0

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25



Hendrik Meijer Library Information Technology Center	8/11/2010			
2.8 Mechanical	200 Points			
	Possible Earned			
2.8.1a Heat source type is appropriate for the application.	5 5			
2.8.1b Condition of the heating source.	15 15			
2.8.2a Cooling source type is appropriate for the application.	5 5			
2.8.2b Cooling exists in appropriate spaces.	5 5			
2.8.2c Condition of cooling source.	10 10			
2.8.3 Condition of the heating and cooling distribution system.	20 20			
2.8.4 Condition of the terminal devices.	20 20			
2.8.5 Condition of the air handling equipment.	20 20			
2.8.6 Condition of controls.	20 20			
2.8.7 Ventilation effectiveness.	10 10			
2.8.8 Condition of the sanitary system.	10 10			
2.8.9 Condition of the storm system.	10 10			
2.8.10 Plumbing fixtures are adequate for building occupancy	10 10			
2.8.11 Condition of exterior water supply.	10 10			
2.8.12 Condition of the internal water distribution system.	10 10			
2.8.13 Speciality classrooms (labs, shops, etc.) are equipped with the appropriate plumbing fixtures.	0 0			
2.8.14 Condition of drinking fountains.	10 10			
TOTAL - Mechanical	190 190			

#### Notes:

See next page.

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25





**Hendrik Meijer Library Information Technology Center** 

8/11/2010

### 2.8 Mechanical Cont.

- 1 This is a new building and the mechanical and plumbing systems are in excellent condition.
- The building is stand alone for heating and cooling energy and is not connected to the central boilers.



Meijer LIT Center	8/11/2010
2.9 Electrical	150 Points
2.9.1 Condition of the electrical service.	Possible Earned  25  20
2.9.2 Interior building and exterior building lights.	25 25
2.9.3 Condition / capacity of distribution and branch panels.	20 20
2.9.4 Condition site lighting.	15 15
2.9.5 Emergency lighting is provided and meets current egress requirements.	15 13
2.9.6 Condition of receptacles and circuiting.	10 10
2.9.7 Lighting controls are provided to meet energy code.	10 8
2.9.8 Condition of public address system.	0 0
2.9.9 Condition of clock system.	0 0
2.9.10 Emergency power is provided by a generator.	10 0
TOTAL - Electrical	130 111

Maximum Points	Non-Existent 0%	Very Inadequate 1-29%	Poor 30-49%	Borderline 50-69%	Satisfactory 70-89%	Excellent 90-100%
5	0	1	2	3	4	5
10	0	2	4	6	8	10
15	0	3	6	9	12	15
20	0	4	8	12	16	20
25	0	5	10	15	20	25





**Hendrik Meijer Library Information Technology Center** 

8/11/2010

### 3.0 Recommendations

This section is intended to document and quantify recommended items / improvements noted during the building assessment. This section is included as a means of quantifying improvement cost through a conceptual estimate. These costs are placeholders of potential value to a recommended item. They only attempt to give an estimated dollar value to a recommended item. This section is designed as a tool to demonstrate the potential costs of recommendations / improvements and provide a comparison based on these costs to other buildings in the district. These costs broken down into recommended time lines based on a 5 year, 10 year and 15 year time table.

Recommendations to be performed within 1 to 5 years	Area / Qty.	*Cost per	Total
Recommendations to be performed within 1 to 5 years	Alca / Wiy.	Cost per	1 Otal \$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

TOTAL - 1 to 5 years



Hendrik Meijer Library Information Technology Center		8/11/2010		
Recommendations to be performed within 6 to 10 years	Area / Qty.	*Cost per	Total	
		оссов рег	\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			<b>\$</b>	
			\$ \$	
			Ψ	
OTAL - 6 to 10 years		[	\$	
Recommendations to be performed within 11 to 15 years	Area / Oty	*Coot nor	Total	
	Area / Qty.	*Cost per	Total \$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
			\$	
OTAL - 11 to 15 years		[	\$	
			^	
GRAND TOTAL			\$	

<sup>\*</sup> The cost reflect total project costs and include: Architectural fees, Construction Management fees, Building Permit fees, moving costs, abatement costs, etc.

